Rev-Jet
Enhanced Energy System

LOADING PROCEDURE INSTRUCTIONS

Place plug onto Rev-Jet tool.



Insert plug into threaded end of 6 inch extension barrel.

Firmly seat the plug.



Properly seated plug.



Uscrew protective barrel cap.



Screw on extension barrel.

Fill the barrel with water.

Load ammo by GENTLY pumping and pressing downward to expel excess water.

Hold Barrel vertically and screw on breech securely.



CDC
CONCEPT DEVELOPMENT CORPORATION

P.O. BOX 18970 FOUNTAIN HILLS, AZ 85269-8970 • (800) 472-4405 • WWW.EOD-TECHNOLOGIES.COM